

## ROCLA AGV SAFETY SCANNER UPDATE



Dear customer,

We would like to inform you, that production of Sick Safety Laser Scanner PLS and the Safety Laser Scanner Interface LSI has ended and therefore the scanner has become obsolete.

New units are not available anymore. Not even as a spare part.

Reparation of broken units is still possible but can be time consuming.

Sick PLS is not directly exchangeable with any other component. Therefore an upgrade must take place. PLS scanner can be upgraded to a more advanced next generation scanner, S3000.

Upgrade is evaluated separately case by case, but here are some examples of what the upgrade means:



### 1. Standalone PLS

- PLS is replaced with an S3000
- no major mechanical changes
- new S3000 STANDARD scanner
- reconnection of scanner cable
- programming
- commissioning

### 2. PLS with LSI

- PLS and LSI are replaced with an S3000
- no major mechanical changes
- new S3000 PROFESSIONAL scanner
- engineering
- cabling and wiring changes
- programming
- commissioning

### 3. 2xPLS with LSI

- 2xPLS and LSI are replaced with 2xS3000
- no major mechanical changes
- new S3000 PROFESSIONAL scanner
- new S3000 REMOTE scanner
- engineering
- cabling and wiring changes
- programming
- commissioning

Please do not hesitate to contact us, if you have any questions or if you need further information about the upgrade:

Rocla AGV Services at +358 20 778 1452, or [mika.laakkonen@rocla.com](mailto:mika.laakkonen@rocla.com)