

End of System 7S/SC repair service

Dear Customer,

As we have previously informed in Status statement from 2011, the repair services for System 7S and 7SC hardware will end in December 2014.

Parts received for repair before 12.12.2014 can be handled normally.

Affected products include for example the following:

All ACC70 products

ACC70 S
ACC70 II BASIC BLACK
ACC70 S WIRE
ACC70 S LASER
ACC70 SC LASER
ACC70 SC SPOT

All ACC70 Sys/Nav cards

ACC70 S WIRE NAV
ACC70 S WIRE SYS
ACC70 SC SYS IV LASER
ACC70 NAV IV
ACC70 S SYS IV 232 LASER
ACC70 NAV IV SPOT

All ACC70 MPMCII cards

ACC70 II MPMC III
ACC70 SC MPMC III

All ACC70 RCF II / RegCom II cards

ACC70 RCF II
ACC70 REGCOM II
ACC70 I/O 15/14 IV

BIV3 24V
CRA70 TOP CABLE POSITION
CRA70 SIDE CABLE POSITION
MCD70III
MCD7
OP7
IM70
PLD7II CL
PLD7II RS422

To ensure uptime and to make your System 7S installations future proof we offer an upgrade path to NDC8. The Upgrade Program offers possibilities to seamlessly upgrade a System7S to NDC8, vehicle by vehicle.

Please consult our staff for further details and options.

More information available from your personal contact or agvservices@rocla.com