

ROCLA AGV SAFETY SCANNER AVAILABILITIES

Dear customer,

As we have informed you earlier, the production of Sick Safety Laser Scanner PLS and the Safety Laser Scanner Interface LSI ended already in 2008.

Now the repair and exchange services for these items are ending as well.

The last repair/exchange units can be taken in no later than Nov.30th 2015

As Sick PLS is not directly exchangeable with any other component a safety equipment upgrade is needed. We recommend the PLS scanners to be upgraded to a more advanced next generation scanner, S3000.

Upgrade is evaluated separately case by case, but here are some examples of what the upgrade means:

1. Standalone PLS

- PLS is replaced with an S3000
- no major mechanical changes
- new S3000 STANDARD scanner
- reconnection of scanner cable
- programming
- commissioning

2. PLS with LSI

- PLS and LSI are replaced with an S3000
- no major mechanical changes
- new S3000 PROFESSIONAL scanner
- engineering
- cabling and wiring changes
- programming
- commissioning

3. 2xPLS with LSI

- 2xPLS and LSI are replaced with 2xS3000
- no major mechanical changes
- new S3000 PROFESSIONAL scanner
- new S3000 REMOTE scanner
- engineering
- cabling and wiring changes
- programming
- commissioning

If you have any questions or if you need further information about the upgrade please do not contact your direct contact person or Services sales at service.sales@rocla.com Tel: +358 20 778 1555