

14.12.2017

FSA II controllers – End of service

According to the Rocla policy for the life cycle of a products, the FSA II motor controllers will reach the “End-Of-Life” state in March 2017. This means that the repair and exchange services will end and we can no longer guarantee repairs or support for it.

The affected components include the full range of FSA II motor controllers from FSA23 II to FSA200 II.



Exchange order returns and parts received for repair before February 28th 2017 can be handled normally.

In order to ensure the long-term usability of your equipment it would also be beneficial to consider to update your system with the latest technology.

For more information contact AGV Service sales at service.sales@rocla.com or +358 20 778 1555